

OMC INTERNATIONAL LABS
Shipping/Packaging



Thank you for allowing us to do business with you.

To prevent the specimens from damages or contamination, we ask for the following:

Powder Samples

When packaging powder, please use a clean and not previously used zip-lock bag.

Do not touch powder with cloth or bare hands. Use a plastic or metal scoop to fill zip-lock bag, take air out of the bag, close tightly and label. Please label bag with below information:

- Manufacturer
- Powder lot or batch number
- Sample identification, if any.
- Date
- Company name
- MSA # if applicable, if not OMC will advise upon receipt of specimen.

Depending on the amount of test, the powder quantity may vary.

Nace SP0394 Table 1 = 1-2 lbs.

Nace SP0394 Table 2 = 6-8 lbs.

Please provide Manufacturer data sheet along with powder.

Coated Samples

When packaging coated specimens, please protect with a clean cloth, bags, plastic or any other material that may help prevent damage to the coating.

Label box or each sample with the following:

- Powder information used (Lot/batch and manufacturer)
- Sample identification, if any.
- Date
- Company name
- MSA # if applicable, if not OMC will advise upon receipt of specimen.

Let us know if you would like for OMC to pick up your samples or if you would like to ship to the address below:

 [1430 Vander Wilt Lane Suite E, Katy TX 77449](https://www.google.com/maps/place/1430+Vander+Wilt+Lane+Suite+E,+Katy,+TX+77449)

OMC INTERNATIONAL LLC. LABORATORY.